

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,385,716 B1  
APPLICATION NO. : 09/388891  
DATED : June 10, 2008  
INVENTOR(S) : Claus Skaanning

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 27, after "a" delete "is".

In column 13, line 38, after "the" delete "8d".

In column 13, lines 38, above "9" insert -- 8d --.

In column 16, lines 22-48, below "TABLE 8" delete  
" "

	Yes	No
1) Media 12		
2) Paper path dirty	22	
3) Environmental conditions	6	
4) Toner cartridge problems	35	->90
a) Defective toner cartridge	10	
b) Improperly seated toner cartridge	5	
c) Toner distribution	85	->25
5) Transfer roller problems	20	
a) Defective or dirty transfer roller	25	
b) Improperly seated transfer roller	65	
c) Wear out transfer roller	10	
6) Incorrect application settings	45	
a) Economode/draft mode on	75	
b) 300/600 dpi set to 300 dpi	15	
c) Other settings set wrong	10	
7) Incorrect printer driver settings	27	
a) Economode set on	80	
b) 300/600 dpi set to 300 dpi	15	
c) Other settings set wrong	5	
8) Incorrect control panel settings	2	
a) Economode/draft mode set on	85	
b) 300/600 dpi set to 300 dpi	5	
c) Print density set too low	10	
9) Corrupt data flow	1	
10) Wrong driver used	15	
11) Other problems	10	
a) Temporary problem	10	
b) Permanent problem	90	"

and insert

	Yes	No
-- 1) Media 12		
2) Paper path dirty	22	
3) Environmental conditions	6	
4) Toner cartridge problems	35	->90
a) Defective toner cartridge	10	
b) Improperly seated toner cartridge	5	
c) Toner distribution	85	->25
5) Transfer roller problems	20	
a) Defective or dirty transfer roller	25	
b) Improperly seated transfer roller	65	
c) Wear out transfer roller	10	
6) Incorrect application settings	45	
a) Economode / draft mode on	75	
b) 300 / 600 dpi set to 300 dpi	15	
c) Other settings set wrong	10	
7) Incorrect printer driver settings	27	
a) Economode set on	80	
b) 300 / 600 dpi set to 300 dpi	15	
c) Other settings set wrong	5	
8) Incorrect control panel settings	2	
a) Economode / draft mode set on	85	
b) 300 / 600 dpi set to 300 dpi	5	
c) Print density set too low	10	
9) Corrupt data flow	1	
10) Wrong driver used	15	
11) Other problems	10	
a) Temporary problem	10	
b) Permanent problem	90	--, therefor.

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,385,716 B1  
APPLICATION NO. : 09/388891  
DATED : June 10, 2008  
INVENTOR(S) : Claus Skaanning

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 18, line 44, delete "C<sub>ix</sub>=yes" and insert -- C<sub>i</sub>=yes --, therefor.

In column 21, line 8, delete "A1" and insert -- A<sub>1</sub> --, therefor.

In column 21, line 9, delete "A2" and insert -- A<sub>2</sub> --, therefor.

In column 30, line 23, after "that the" delete "action".

Signed and Sealed this

Fourteenth Day of October, 2008



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*